

Table 8.2 G12 Corridor Improvement Concepts Summary

Project Area	Improvement Concepts
1. San Miguel Canyon Road, US 101 to Castroville Boulevard (Prunedale)	 Traffic Signal at Langley Canyon Road Roundabout at Castroville Boulevard 2 Lanes northbound between Moro Road and Castroville Boulevard Sidewalk between Moro Road and Langley Canyon Road Class I Bake Path connecting from Bike Lane to Prunedale North Road Class II Bike Lane northbound between Prunedale North Road and Moro Road
2. San Miguel Canyon Road, north of Castroville Boulevard to Hall Road	 Echo Valley Road – Alternatives: Roundabout (preferred) and Center Left Turn Lane south to Pond Derosa Lane, or Center Left Turn Lane south to Pond Derosa Lane Roundabout at Strawberry Road Center Left Turn Lane between Echo Valley Road and Paradise Road, and between Mark Ryan Estates and Woodland Hill Lane Guardrail north of Hambey Lane
3. Hall Road, San Miguel Canyon Road to Elkhorn Road (Las Lomas)	 Remove channelized right turn at San Miguel Canyon Road/Hall Road traffic signal Sill Road – Alternatives: Roundabout (preferred) or Traffic Signal Realign Las Lomas Drive and Sill Road, construct Roundabout Restrict left turns out at Willow Road Center Left Turn Lane, Frontage Road, and Sidewalk west of Willow Road Roundabout at Elkhorn Road
4. Elkhorn Road Bridge	Widen bridge to install Bike Lanes on both sides, and sidewalk on south side
5. Elkhorn Road/Werner Road/Salinas Road	 G12/Werner Road/Salinas Road – Alternatives: Consolidate intersections into one, construct roundabout, or Install 3 traffic signals Install Traffic Signal at Hillcrest Road Install Traffic Signal at Fruitland Avenue (optional; if meets warrants)
6. Salinas Road/Porter Drive, north of Salinas Road/Elkhorn Road to Pajaro River Bridge (Pajaro)	 Road Diet with Buffered Bike Lanes along Salinas Road (current 4-lane section) south of Pajaro Entry Median and overhead Welcome sign south of Railroad Tracks Class II Bike Lanes (with Buffer where feasible) within Pajaro Continuous 5' sidewalk within Pajaro Flashing Beacons (RRFB) at mid-block crosswalk Reconfigure diagonal on-street parking north of Bishop Street to be separated from roadway Convert Salinas Road minor road approach at Porter Drive to be Right Turn Only out Reconfigure southbound Porter Drive south of San Juan Road to be one lane (remove lane merge) Reconfigure southbound approach lane geometry of Porter Drive/Main Street at San Juan Road to have one right turn pocket, one thru lane, and two left turn lanes (one continuous lane, one turn pocket) Install overhead sign for southbound traffic